

SpeedTube™

CASE IH SpeedTube Row Unit Kits have shipped. We have identified variability in CASE IH firming points that can cause fit-up issues into the Precision Planting SpeedTube Shoe. If fit-up problems occur, there are three options to resolve:

1. Move firming point from another row(s) to improve fit-up with new shoe.
2. Grind down the area of the firming point that fits into the new shoe and is causing the interference.
3. Purchase new firming points from CASE IH dealer. Ensure that the new firming points are narrower than existing firming points that do not fit.

Refer to the following image for interference area

