

Technical Bulletin: WaveVision Harness Length Change



Problem: There has been a running design change that has shortened the WaveVision sensor harness. Kinze 2000 series planters with WaveVision sensors AND a factory installed planter harness may not have enough harness on the sensor to reach the connection on the planter harness.

Solution: To solve the issue, all Kinze 2000 series planters will require a 725061 Seed Tube Sensor Extension with each row of WaveVision installed.

955290_01 9/12



Technical Bulletin: WaveVision Harness Length Change



Problem: There has been a running design change that has shortened the WaveVision sensor harness. Kinze 2000 series planters with WaveVision sensors AND a factory installed planter harness may not have enough harness on the sensor to reach the connection on the planter harness.

Solution: To solve the issue, all Kinze 2000 series planters will require a 725061 Seed Tube Sensor Extension with each row of WaveVision installed.

955290_01 9/12

