

Old/ Standard Flagships/ x250s



New/ 2021 x250s



the flow sensor mounting plate can't move forward completely because of the new curved design

Existing flow sensor w/mount



New x250 cover plate

trim



Trim edge w/grinder

