


vDrive®

vDrive 2.0 — JD Minihopper Rear Post Modification

Due to small variances in manufacturing tolerances, vDrive 2.0 may occasionally interfere with the rear post on JD minihoppers. If interference is present (below, left), use a dremel or cutting tool to modify the bracket as shown (below, right).



Completed Modification

