

Service Bulletin: Serial Cable Adapter to allow communication from the Rawson Controller to the 20/20 SeedSense





March 8, 2011

- Solution provided to replace the Null Modem and Gender Changer on the Serial Cable (727149, 727150) for RowFlow systems connected to Rawson Controllers.
- Required on 2010 RowFlow Modules with serial numbers through 8101196

What's included:

727192 Adapter Cable



Install:

1. Remove the Null Modem and Gender Changer from the 727150 or 727149 Serial Cable running between the RowFlow Base Harness and the Rawson Controller in the cab.
2. Install the 727192 Adapter cable between the serial cable and the Base Harness or Controller.
3. Update to 5.0 or newer software.
4. The RowFlow and Rawson will now have two-way communication to improve RowFlow diagnostics on the Rawson system.