


Instructions for SmartFirmer Bootloader File (955942)

This update is only needed for SmartFirmers that are being install on a Gen 2 20/20 system and have a label on the box indicating a minimum software requirement (see below). If this update is unintentionally installed on a SmartFirmer that does not require it, it will NOT be negatively impacted in any way



Step 1:

Download the bootloader file zip folder on the Product Resources page at cloud.precisionplanting.com under the SmartFirmer section

Step 2:

Unzip the folder and move the two files onto the root directory of a blank USB drive

Step 3:

Power down the display and insert the USB drive containing the bootloader files into the side of the 20/20 display

Step 4:

Make sure that the SmartFirmers are plugged into the CAN expansion hub at this time


Step 5:

Power on the display. Once the display recognizes and imports the bootloader file, you will see a message saying, "Files copied, please remove USB disk to continue". Remove the USB drive and the display will reboot automatically.

Note: If you did not receive this message on start up then the display did not recognize the bootloader file and the update will not work

Step 6:

Once the display reboots navigate to the diagnose page to confirm that the SmartFirmers are updating firmware



After the SmartFirmers have completed updating firmware, installation is complete